



Lancaster Road, Carnaby Industrial Estate, Bridlington, East Yorkshire, YO15 3QY, UK

Truck Dismantling & CKD | Truck Engines & Truck Spare Parts | FCL-LCL Container Loading & Shipping

Scania 93/113



£POA

Scania 93/113 Rear Lift Axle Assy REMOVED FROM SCANIA 93/113 TRACTOR UNITS & RIGID TRUCKS

Product Details		
Category/Type:	Axles	Function: -
Make/Model:	Scania 93/113	Transmission: -
Year:	-	Axle Config: Rear Lift
Mileage:	-	Cab Type: -
Stock Ref:	SCALAA-0201	